## IN THE DRAWINGS

A replacement sheet and an annotated sheet showing changes made have been attached as an appendix to this paper. In Figure 8 of the drawings, "508" in the bottom row of the table has been changed to "506". No new matter has been added as a result of this amendment.

Serial No. 09/617,480 Examiner: Sefcheck, Gregory B.

Art Unit 2662 3COM-2366.MCD.US.P



## Replacement Sheet

·	LAN <u>152</u>	Modem <u>150</u>	ISDN <u>154</u>
Relay <u>507</u>	Α	-	В
Relay <u>508</u>	-	Α	В
Relay <u>506</u>	Α	-	-